


DASHED OR PLAT REDUCED DIMENSIONS
 DRAINAGE DITCH OR CENTERLINE OF CREEK
 EDGE OF WATER BODY OR SHORT LINE
 WOOD FENCE
 CHAIN LINK FENCE
 PASTURE OR BARBED WIRE FENCE
 INDICATES A BREAK IN SCALE
 OVERHEAD POWER OR TELEPHONE LINE
 POWER POLE

BSL- Building Setback Line
 CMF- Concrete Monument Found
 CRF- Capped Rubber Found
 CRS- Capped Rubber Set (Borden-13402)
 CTIF- Capped Top Iron Found
 CC- Digger Chain Found
 DIST- Distributed
 ELE- Elevation G.S.
 NL- Not Located
 OTIF- Open Top Iron Pipe Found
 POS- Point of Beginning
 POC- Point of Commencement
 RLA- Recorded and Actual
 RSP- Rubber Found
 ROW- Right-of-Way
 TBM- Temporary Benchmark



STATE OF ALABAMA
COUNTY OF

BALDWIN

SUBDIVISION PLAT/DEEDS OF RECORD

SOURCE OF INFORMATION

12/11/2017

DATE OF ACTUAL FIELD SURVEY

OWNER: DAVID C. MARION

SURVEY TYPE: Boundary Survey

STANDARDS OF PRACTICE FOR

LOT 71, BLOCK 71, Unit or Addition

GULF SHORES, Alabama, as found recorded in Map Bk 4 Pg 144

DATED JULY 31, '17, as published by the FEDERAL EMERGENCY

NEEDS NOT WARRANT SAID PROPERTY FROM FLOODING. THE