TERMINIX

JEROME WILLIAMS
Customer name

[redacted]
Customer phone

1785168
Service agreement number

13782 Mannich Ln
Foley , AL 36535
Service Address

05/23/2026
Today's date

Next service:
April/2027

MOBILE NORTH
1032 N University Blvd
Mobile, AL 36608
1 (800)837-6464

Hi JEROME, Thank you for choosing Terminix®. Here are some notes about today's visit:



CHRISTOPHER BURGE
Service technician

Phone: -
Email: **christopher.burge@terminix.com**
Employee number: **132894**
License/cert: -
Supervisor: **POPE, RICKY L.**
Supervisor license/cert: **2005298**

Subterranean Termite Inspection
Purpose of appointment

Annually
Service frequency

8:25 AM – 8:26 AM
Arrival/departure time

TODAY'S CONDITIONS

Temp	Wind speed	Wind direction	General conditions
77 °F	**5.75 MPH**	**SE**	**Clear**

PROPERTY INFORMATION:

Is there visible exterior damage? No

Is there visible exterior termite activity? No

Are there any exterior inaccessible areas? No

Are there visible conducive conditions found on the exterior: No

HERE'S WHAT I FOUND:

Did not have access for full mandatory service, please call within 30 days to schedule completion.



Other Treatment Photos

Locked Gate

MY TREATMENT NOTES:

Your service is now complete. If you need something before your next service appointment, don't hesitate to let us know. Thank you for letting us protect your home.

PRODUCT LABELS & SAFETY DATA SHEETS

Product Labels & Safety Data Sheets, please visit: https://lycensed.com/orgs/terminix/public/chemical_documents

For NY customers, please select 'NY' as your locale

NOT ENROLLED IN AUTOPAY?

Paying is easy with MyAccount.
There's no need to track down the checkbook and stamps. Simply go online to Terminix.com/My-Account to pay quickly and easily.

Billing Address
PO Box 411
Magnolia Springs, 36555

SUMMARY OF TODAY'S CHARGES

Balance due:	$ 0.00
Current charges:	$ 0.00
Subtotal:	$ 0.00
Tax:	$ 0.00
Total:	$ 0.00

Customer Signature: Customer not at home **Date:**

JEROME WILLIAMS

Recommended and Service provided by:

Technician Signature:  **Date:** 05/23/2026

CHRISTOPHER BURGE

In case of poisoning call Poison Control Center @1-800-222-1222

IT IS IMPORTANT TO NOTE THAT THIS INSPECTION IS ONLY FOR THE TERMITE SPECIES LISTED AS CONTROLLED OR PROTECTED AGAINST IN YOUR PLAN, NOTWITHSTANDING THAT THERE ARE SECTIONS BELOW FOR BOTH SUBTERRANEAN AND DRYWOOD SPECIES. IT IS ALSO IMPORTANT TO NOTE THAT YOUR TERMITE PLAN ONLY COVERS THE TERMITE SPECIES SPECIFICALLY LISTED AS CONTROLLED OR PROTECTED AGAINST IN YOUR PLAN. CONSEQUENTLY, YOUR TERMITE PLAN MAY NOT PROVIDE FOR CONTROL OF, PROTECTION FROM, OR SERVICE FOR SUBTERRANEAN TERMITES (Reticulitermes spp., Heterotermes spp.), FORMOSAN TERMITES (Coptotermes spp.), OR DRYWOOD TERMITES (Kalotermes spp., Incisitermes spp., Cryptotermes spp.). PLEASE SEE YOUR TERMITE PLAN TO DETERMINE WHICH OF THE TERMITE SPECIES ARE COVERED UNDER YOUR PLAN AND WERE THUS INSPECTED FOR. IT IS ALSO IMPORTANT TO NOTE THAT DRYWOOD TERMITES ARE NOT NORMALLY FOUND IN EVERY AREA OF EVERY STATE, THUS THIS INSPECTION DID NOT INCLUDE AN INSPECTION FOR DRYWOOD TERMITES UNLESS 1) THE PROPERTY INSPECTED IS LOCATED IN AN AREA OF FL, HI, TX, AZ, NM, AL, MS, LA, GA, SC OR NC WHERE DRYWOOD TERMITES NORMALLY OCCUR AND 2) THE SPECIES LISTED AS CONTROLLED OR PROTECTED AGAINST IN YOUR PLAN INCLUDES DRYWOOD TERMITES. PLEASE ALSO SEE YOUR TERMITE PLAN FOR ADDITIONAL CONDITIONS AND LIMITATIONS WHICH ARE INCORPORATED HEREIN BY REFERENCE AND WHICH SHALL CONTROL IN THE EVENT OF ANY CONFLICT WITH THIS INSPECTION.

JEROME WILLIAMS Customer name [redacted] Customer phone	1785168 Sales agreement number	13782 Mannich Ln Foley , AL 36535 Service Address	08/27/2025 Today's date	**Next service:** April/2026 **MOBILE NORTH** 1032 N University Blvd Mobile, AL 36608 1 (800)837-6464

Hi JEROME, Thank you for choosing Terminix®. Here are some notes about today's visit:

DRAVEN MATHIAS Service technician draven.mathias@terminix.com	Employee number: **131552** License/Cert: **-** Supervisor: **POPE, RICKY L.** Supervisor License/Cert: **2005298**	Subterranean Termite Inspection Purpose of appointment	9:00 AM – 9:15 AM Arrival/departure time	Annually Service frequency

TODAY'S CONDITIONS

Temp	Wind speed	Wind direction	General conditions
74 °F	**8.05 MPH**	**ENE**	**Clouds**

PROPERTY INFORMATION:

Did you find visible interior termite activity? No

Are there any interior inaccessible areas? No

Are there visible conducive conditions? No

Is there visible exterior damage? No

Is there visible exterior termite activity? No

Are there any exterior inaccessible areas? No

Are there visible conducive conditions found on the exterior: No

HERE'S WHAT I FOUND:

Stucco na
The support seen under the crawl space
Some what I couldn't fit into the crawl space

SERVICE VISIT PICTURES
View pictures and notes from your service technician with MyAccount at Terminix.com/My-Account.

MY TREATMENT NOTES:

Your service is now complete. If you need something before your next service appointment, don't hesitate to let us know. Thank you for letting us protect your home.

PRODUCT LABELS & SAFETY DATA SHEETS

Product Labels & Safety Data Sheets, please visit: https://lycensed.com/orgs/terminix/public/chemical_documents

For NY customers, please select 'NY' as your locale

NOT ENROLLED IN AUTOPAY?

Paying is easy with MyAccount.
There's no need to track down the checkbook and stamps. Simply go online to Terminix.com/My-Account to pay quickly and easily.

Billing Address
PO Box 411
Magnolia Springs, 36555

SUMMARY OF TODAY'S CHARGES

Balance due:	$ 0.00
Current charges:	$ 0.00
Subtotal:	$ 0.00
Tax:	$ 0.00
Total:	$ 0.00

Customer Signature:  **Date:** 08/27/2025

JEROME WILLIAMS

Recommended and Service provided by:

Technician Signature:  **Date:** 08/27/2025

DRAVEN MATHIAS

In case of poisoning call Poison Control Center @1-800-222-1222
IT IS IMPORTANT TO NOTE THAT THIS INSPECTION IS ONLY FOR THE TERMITE SPECIES LISTED AS CONTROLLED OR PROTECTED AGAINST IN YOUR PLAN, NOTWITHSTANDING THAT THERE ARE SECTIONS BELOW FOR BOTH SUBTERRANEAN AND DRYWOOD SPECIES. IT IS ALSO IMPORTANT TO NOTE THAT YOUR TERMITE PLAN ONLY COVERS THE TERMITE SPECIES SPECIFICALLY LISTED AS CONTROLLED OR PROTECTED AGAINST IN YOUR PLAN. CONSEQUENTLY, YOUR TERMITE PLAN MAY NOT PROVIDE FOR CONTROL OF, PROTECTION FROM, OR SERVICE FOR SUBTERRANEAN TERMITES (Reticulitermes spp., Heterotermes spp.), FORMOSAN TERMITES (Coptotermes spp.), OR DRYWOOD TERMITES (Kalotermes spp., Incisitermes spp., Cryptotermes spp.). PLEASE SEE YOUR TERMITE PLAN TO DETERMINE WHICH OF THE TERMITE SPECIES ARE COVERED UNDER YOUR PLAN AND WERE THUS INSPECTED FOR. IT IS ALSO IMPORTANT TO NOTE THAT DRYWOOD TERMITES ARE NOT NORMALLY FOUND IN EVERY AREA OF EVERY STATE, THUS THIS INSPECTION DID NOT INCLUDE AN INSPECTION FOR DRYWOOD TERMITES UNLESS 1) THE PROPERTY INSPECTED IS LOCATED IN AN AREA OF FL, HI, TX, AZ, NM, AL, MS, LA, GA, SC OR NC WHERE DRYWOOD TERMITES NORMALLY OCCUR AND 2) THE SPECIES LISTED AS CONTROLLED OR PROTECTED AGAINST IN YOUR PLAN INCLUDES DRYWOOD TERMITES. PLEASE ALSO SEE YOUR TERMITE PLAN FOR ADDITIONAL CONDITIONS AND LIMITATIONS WHICH ARE INCORPORATED HEREIN BY REFERENCE AND WHICH SHALL CONTROL IN THE EVENT OF ANY CONFLICT WITH THIS INSPECTION.

Survey of Conditions Favorable to Termite and Pest Infestations

Today, we gave your home a thorough inspection. Pay special attention to anything marked in the "no" column, as these are conditions that can lead to termite and pest problems. Ask your Terminix expert about the best plan of action.

JEROME WILLIAMS
Homeowner Name

13782 Mannich Ln
Address

Foley | AL | 36535
City | State | Zip

[redacted] | 0
Home Phone | Work Phone

0
Email Address

Exterior	Y	N	Comments
1. **Do gutters, downspouts, and ground slope direct water away from structure?** Missing or misdirected gutters or downspouts - or an improper slope that keeps water from draining away from a structure - can lead to infestation and structural deterioration.	☑	☐	
2. **If a dirt-filled porch is present, is it sealed away from the home?** Soil close to a wood structure is an ideal habitat for termites - and can lead to infestation and structural deterioration.	☑	☐	
3. **Does home have Rigid Board Insulation (RBI), such as Dri-Vit or "EFIS", that is more than 3" above grade or meets State Minimum Standards?** Moisture retained by RBI promotes infestations, and provides easy pathways for pests throughout the structure's exterior.	☐	☑	Stucco na
4. **Is structure clear of attached slab, patio, walk or drive?** Attached slabs provide concealed pathways for infestations.	☑	☐	
5. **Is the top of the foundation clear of mulch? Is mulch less than 2" deep?** Organic mulch more than 2" deep or above top of foundation can promote moisture or pest entry.	☑	☐	
6. **Are wood attachments (deck, fence, trellis, etc.), firewood, and outside storage clear of the structure?** Wood decks, fences, trellises, firewood, and storage structures may give subterranean termites a way in.	☑	☐	
7. **Is the air flow at foundation vents obstruction-free?** Anything blocking vents can reduce crawlspace ventilation, elevate moisture levels and promote wood decay or subterranean termite infestation.	☑	☐	
8. **Is the structure's exterior free of heavy vegetation?** Heavy vegetation can lead to excess moisture and structural deterioration, can give pests and termites a place to live, and can prevent a thorough inspection.	☑	☐	
9. **Is the foundation or masonry free of settlement cracks?** Cracks can give subterranean termites a way to get in.	☑	☐	
10. **Is home free of earth-to-wood contact?** Termites readily attack places where wood meets the soil. Such wood absorbs moisture, making it prone to decay and wood-destroying insects.	☑	☐	

Crawlspace	Y	N	Comments
1. **Are crawlspaces accessible?** Inaccessible areas can limit our ability to inspect thoroughly.	☑	☐	
2. **Is sub-area soil free of wood scraps and stored items?** Cellulose debris can be food for subterranean termites. Stored materials may provide living space for other pests, and may prevent a thorough inspection.	☑	☐	
3. **Is crawlspace free of standing water? Is drainage adequate?** These conditions can raise moisture levels in wood framing, and may foster wood decay fungi or wood-destroying pests.	☑	☐	
4. **Is ventilation adequate?** Inadequate crawlspace ventilation can lead to elevated moisture, wood decay fungi, and wood-destroying pests.	☑	☐	
5. **Is there adequate clearance between floor joists and soil?** Inadequate clearance can prevent a thorough inspection.	☑	☐	

Interior (including basements and attics)	Y	N	Comments
1. **Is structure free of plumbing leaks?** Leaks can raise moisture levels, promote wood decay fungi, and foster wood-destroying pests.	☑	☐	
2. **Are slab floors and walls free of settlement cracks?** Cracks can provide concealed entry for subterranean termites.	☑	☐	
3. **Are foundation walls and slab free of embedded wood?** Wood members or trim embedded in concrete slab floors or masonry foundation walls may lead to elevated wood moisture levels, promote wood decay fungi, and foster wood-destroying pests.	☑	☐	
4. **Is the home free of a hollow block foundation or piers?** Hollow block foundations and piers can permit concealed access by termites.	☐	☑	The support seen under the crawl space
5. **Are all areas accessible?** Inaccessible areas can limit our ability to inspect thoroughly.	☐	☑	Some what I couldn't fit into the crawl space

Any findings on this survey reflect evidence that was visible and accessible at the time of inspection. This form is for informational purposes only, and is not to be used for real estate closings or relied upon by anyone other than the current owner of the property.