




NOTES:

1. Capped rebar found at each corner(23347LS).
2. Bearings referenced to record bearing for West line of Lot 73.

William Long Schmitt
Kelli Dalloway Davidson

STATE OF ALABAMA)
COUNTY OF BALDWIN)

I, Robert B. Moseley, a registered Land Surveyor in the State of Alabama, hereby state that all parts of this survey and drawing have been completed in accordance with the current requirements of the Standards of Practice for Surveying in the State of Alabama to the best of my knowledge, information and belief.